

**From:** [Arredondo, Alonzo](#)  
**To:** [Moore, Gary](#)  
**Subject:** Falcon Refinery - Site Visit  
**Date:** Friday, March 08, 2013 9:29:02 PM

---

Gary,

I traveled to the Falcon Refinery site today. The site appears the same as the last time Lazarus was on site.

### **Tank 13**

Today BBB Tank Service was onsite reinstalling the door to Tank 13. A portion of the floor has been replaced in the tank.

WelFab, the tank cleaning service gathered their tank cleaning equipment. WelFab has moved the contaminated surface soil that was adjacent to the Tank 13 clean-out door, and placed it on plastic in a small area immediately next to (just south of) Superior's trench/pit.

### **Crude Oil Gathering Trench/Pit**

The trench/pit that Superior used to intercept/gather the crude oil leaking from Tank 13 still remains. Currently the pit contains water and oil.

I've included photos that show the pit and affected soils.

### **Tank 12**

As you are aware, this tank requires repair. There is standing water about the perimeter of the tank. The water originates from a leak around the lower left side of the clean-out door.

I'll be sending additional photos in e-mail messages that follow.

Please contact me if you have any questions.

Alonzo

***Alonzo G. Arredondo, P.G.***  
***Senior Geologist***



303 W. Ave A, Kingsville, TX 78363  
C: 361.522.1935

[LinkedIn](#) | [Twitter](#) | [Blog](#) | [Flickr](#) | [www.trcsolutions.com](http://www.trcsolutions.com)

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>



9568129